the play inspection company

Annual Inspection

Mudford Parish Council

Mudford Play Ground

Mudford , Yeovil, BA21 5TE



Unit 5, Glenmore Business Park, Blackhill Road, Poole, Dorset, BH16 6NL
t- 01202 590675 e- info@playinspections.co.uk

www. playinspections .co.uk

Powered by: the play inspection app by the play inspection company

Inspection Scope for RPII Annual Inspectors

This document outlines the RPII scope for inspections undertaken by the Inspectors listed as Indoor and Outdoor Annual Inspectors (where relevant) on the RPII Register of Inspectors when undertaking inspections.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it will be the standard that is current at the time of inspection except where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection, unless they are also explicitly listed here.

For the avoidance of doubt, references to compliance relate only to those aspects that can be assessed visually or manually, within the limitations of a non-dismantling, non-destructive inspection, and without the use of specialist equipment.

The following standards define the technical framework within which inspections are carried out; not all requirements within these standards can be verified during an inspection. The following standards are relevant to all installations of equipment that are publicly accessible to users; this includes public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below):

> BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.
>
> BS EN 1176 Part 7 - ‘Guidance on Installation, Inspection, Maintenance and Operation’ (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, excluding ancillary items).

In the United Kingdom the National Foreword forms an important part to the understanding and implementation of the recommendations set out in this document. It clarifies the application of the document within the UK as best practice guidance, as the document has been used since its initial publication. Therefore, in the UK this standard (BS EN 1176 – Part 7) contains no requirements and needs to be read and implemented as guidance, with the use of the term ‘shall’ therefore becoming a recommendation, as in the term ‘should’.

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standards (BS EN 71 series – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report; any comments will be made using the principles of BS EN 1176 as guidance only, rather than as a formal assessment of compliance.

When water play items, including spray parks, are inspected any comments concerning compliance within the inspection will refer to EN 1176. We have not assessed these against the requirements of EN 17232 (Water play equipment and features).

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

> **BS EN 15312** Free access multi-sports equipment
> **BS EN 14974** Skateparks
> **BS EN 16630** Permanently installed outdoor fitness equipment
> **BS EN 16899** Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with these current standards, and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area (that area which is obviously part of the playground), nominally up to three metres around, the fence line if closer, or other areas as agreed.

Operational inspections only take into consideration defects related to cleanliness, equipment ground clearances, ground surface finishes, exposed foundations, sharp edges, missing parts, excessive wear (of moving parts) structural integrity, wear and vandalism. Routine visual inspections relate only to the most obvious defects such as broken or missing parts, litter, vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

All inspections are non-dismantling, non-destructive and do not include any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a basic manual stability check appropriate to a visual

inspection and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all reasonably accessible equipment and will assess all reasonably accessible parts above the standing surface. For the purposes of this inspection, “reasonably accessible” means accessible without the use of specialist access equipment, tools, or unsafe working practices. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment.

Ancillary equipment will be assessed using the inspector’s knowledge and experience of the standards named in this document. (Note: Ancillary items are not included in the specific equipment-type parts of the EN 1176 series; hence they are not assessed for compliance with EN 1176 series and are subject to a general safety assessment).

The owner/operator is responsible for the overall safety of the equipment and area.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

> Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of the impact attenuating properties of any surfaces; the identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection; the inspection of any equipment (or part thereof) that is beneath the playing surface (loose-fill materials may be moved to expose foundations); tightening any bolts, hinges or other fixing devices on any apparatus or equipment; assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment; assessing or inspecting any water supplies and/or water features and/or any associated computerised systems (including carrying out any programming); where planting or trees are mentioned in the report no assessments of toxicity, suitability or condition are undertaken – the owner/operator should have suitable inspections provided by a competent person.

The owner/operator should have a ‘design risk assessment’ provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a ‘suitable and sufficient assessment’ of the risks associated with a site or activity. This inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/or that of the inspection company. The owner/operator should always seek the advice of the manufacturer or a competent person when undertaking repairs and/or modifications to equipment.

Responsibility of the Owner/Operator The owner/operator has overall responsibility for the safety, management, and ongoing maintenance of the play equipment and surrounding area. This includes ensuring that equipment is appropriately installed, inspected, maintained, repaired, and managed in accordance with the relevant standards, manufacturer guidance, and applicable legislation

Inspections undertaken by RPII Annual Inspectors contribute to the owner/operator’s discharge of these responsibilities but do not replace the requirement for the owner/operator to carry out suitable and sufficient risk assessments, routine monitoring, and maintenance, or to act on identified defects and recommendations. Responsibility for initiating or undertaking any actions arising from this report rests solely with the Client.

© The Register of Play Inspectors International 4th February 2026

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection recommendations of relevant standards **Inclusion or exclusion within this table does not imply an exhaustive assessment; all inspections and checks are subject to the limitations described within this methodology. Refer to relevant standards for full text**	**Annual Main**	**RPII Annual/ Post Installation Inspection**
6.1 d) Overall levels of safety of equipment (see note 1)	✓	✓ [1]
6.1 d) Overall levels of safety of foundations (see note 1)	✓	✓ [1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	✓	✓ [2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)	✓	✓ [3]
6.1 d) Effects of weather	✓	✓
6.1 d) Presence of rot, decay or corrosion (see note 1)	✓	✓ [1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	✓	✓ [4]
6.1 d) Excavation or dismantling/additional measures	✓	✗
6.2.1 Assessment of glass reinforced plastics (see note 5)	✓	✓ [5]
6.2.1 Inspection of one post equipment (see note 1)	✓	✓ [1]
6.2.4 Undertaking the Operators inspection protocol	✓	✗

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall inspection responsibilities as detailed in the relevant standards. RPII Annual Inspectors may, where readily available, refer to manufacturer installation instructions for general context, but do not check against these in full on any item as inspections are focused on compliance with relevant standards and maintenance defects; the responsibility for ensuring that installation instructions are adhered to lies with the owner and the installer.

[1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.

[2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.

[3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.

[4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance.

[5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

© The Register of Play Inspectors International 4th February 2026

Risk Assessment Matrix

			Scores in the report are multiplication factors of Likelihood x Severity					
			Severity>>					
Likelihood	Very High probability, if the situation is not addressed an accident is almost certain.	5	Very High	VL (5)	L (10)	M (15)	H (20)	VH (25)
	High probability an accident is probable without any added factor.	4	High	VL (4)	L (8)	M (12)	H (16)	H (20)
	Moderate probability an incident is foreseeable.	3	Moderate	VL (3)	L (6)	L (9)	M (12)	M (15)
	Some probability, requires a combination of factors to take place.	2	Low	VL (2)	VL (4)	L (6)	L (8)	L (10)
	No significant probability; lightning strike, freak accident.	1	Very Low	VL (1)	VL (2)	VL (3)	VL (4)	VL (5)
				Very Low	Low	Moderate	High	Very High
				1	2	3	4	5
				No injury likely e.g. damaged or soiled clothing, minor bruising, grazes	Minor injury, laceration or bruising requiring first aid only	Injury requiring medical intervention e.g. cuts requiring stitches	Serious injury including concussions or fracture of long bones	Severe injury involving a potential life changing injury or fatality
				Severity>>				

Powered by The Play Inspection App

Note 1: The total risk scores included within our reports are a multipication factor of the calculated Likelihood and Severity of each finding. Both Likelihood and Severity are given a number between 1 - 5 as shown on the matrix above and these two numbers are then multiplied together to give the total risk score that is shown against defects on the report. Total risk scores can be divided in both directions, i.e. a total risk score of 12 could be a Likelihood (3) x Severity (4) or Likelihood (4) x Severity (3).

Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.

Mudford Play Ground

Inspection Ref: 3200827 Site Ref: 62069

Inspected: 7-September-2026 - 09:32 by Kyle Warrington (RPII Annual Inspector)

Risk Assessment: 10 Low Risk



Location:
There are no specific notes for this site
Disabled Access:
Some accessible features - The area includes limited accessible elements; however, aspects of the layout, surfacing, or equipment may present barriers to use for some people with disabilities without reasonable adjustments or assistance.

8 - Low Risk

Item: Site General
Manufacturer: Owner/Operator
Surface Type: N/A
Item Quantity: 1
Equipment Compliance: Yes
Surface Area Compliance: N/A

Total Findings: 1



Finding 1

There is a potential conflict between the users of the basketball post and the users of the fitness equipment - Monitor and take appropriate action if required

8 - Low Risk

Item: Sign
Manufacturer: Not Identified
Surface Type: N/A
Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 1



Finding 1

There are projecting bolt thread(s) present - Remove excess thread length and deburr or provide cap

8 - Low Risk

Item:	Gate - Self Closing
Manufacturer:	I.A.E. Fencing
Surface Type:	Grass
Item Quantity:	1
Equipment Compliance:	N/A
Surface Area Compliance:	N/A
Total Findings:	2



Finding 1	Finding 2
There are trip hazards present - Remove trip hazard	The gate is closing too quickly (less than 4 seconds) - Take corrective action to ensure that the gate closes in 4-8 seconds from 90 degrees

6 - Low Risk

Item:	Gate - Combination
Manufacturer:	I.A.E. Fencing
Surface Type:	Grass
Item Quantity:	1
Equipment Compliance:	N/A
Surface Area Compliance:	N/A
Total Findings:	2



Finding 1	Finding 2
There is no padlock on the maintenance gate - Provide a padlock to secure the gate	The gate has no drop bolt sleeves and/or drop bolts fitted - Provide drop bolt sleeves and/or drop bolts

4 - Very Low Risk

Item:	Fence - Bow Top
Manufacturer:	Not Identified
Surface Type:	Grass
Item Quantity:	1
Equipment Compliance:	N/A
Surface Area Compliance:	N/A
Total Findings:	1



Finding 1

This item is satisfactory - no work required -

4 - Very Low Risk

Item:	Bench
Manufacturer:	Not Identified
Surface Type:	Grass
Item Quantity:	1
Equipment Compliance:	N/A
Surface Area Compliance:	N/A
Total Findings:	1



Finding 1

This item is satisfactory - no work required -

8 - Low Risk

Item: Teenage Shelter
Manufacturer: Not Identified
Surface Type: Concrete
Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 2



Finding 1

There are trip hazards at the edges of the surface - Remove trip hazard

Finding 2

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding - Treat affected areas and repaint

6 - Low Risk

Item: 1 Bay 2 Seat (Flat)
Manufacturer: Wicksteed Playgrounds
Surface Type: Grass Matrix Tiles
Item Quantity: 1
Equipment Compliance: No
Surface Area Compliance: Yes

Total Findings: 1



Finding 1

The seats are too close to each other as defined in BS EN 1176 Part 2; this is a low risk failure and no remedial action is required - Monitor - No action given the risk assessment

8 - Low Risk

Item: See Saw
Manufacturer: Wicksteed Playgrounds
Surface Type: Grass Matrix Tiles
Item Quantity: 1
Equipment Compliance: Yes
Surface Area Compliance: Yes

Total Findings: 2



Finding 1
The torsion joint is very stiff and difficult to operate - Repair or replace

Finding 2
There are trip hazards present - Remove trip hazard

6 - Low Risk

Item: Activity Trail
Manufacturer: Wicksteed Playgrounds
Surface Type: Grass
Item Quantity: 1
Equipment Compliance: No
Surface Area Compliance: Yes

Total Findings: 3



Finding 1
The ropes/nets are worn/damaged in places - Monitor for any further deterioration and repair or replace as required

Finding 2
The connecting links are in excess of 8.6mm and less than 12mm and fail the requirements of BS EN 1176 Part 1; clause 4.2.13, Chains - Monitor - No action given the risk assessment

Finding 3
The surface has subsided in some areas - Monitor for any further deterioration and repair as required

8 - Low Risk

Item: Multi Play (Junior)
Manufacturer: Wicksteed Playgrounds
Surface Type: Grass Matrix Tiles
Item Quantity: 1
Equipment Compliance: No
Surface Area Compliance: Yes

Total Findings: 4



Finding 1
The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding - Treat affected areas and repaint

Finding 2
The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 for head and neck entrapment in the netting due to a loose rope connector - Adjust and secure the rope connector to remove the entrapments

Finding 3
The ropes/nets are worn/damaged in places - Monitor for any further deterioration and repair or replace as required

Finding 4
The adjacent foliage is overhanging the falling space - Cut back and maintain a clear falling space

4 - Very Low Risk

Item: 1 Bay 2 Seat (Cradle)
Manufacturer: Wicksteed Playgrounds
Surface Type: Grass Matrix Tiles
Item Quantity: 1
Equipment Compliance: Yes
Surface Area Compliance: Yes

Total Findings: 1



Finding 1
This item is satisfactory - no work required -

10 - Low Risk

Item: Basketball Post
Manufacturer: Adidas
Surface Type: Bitmac
Item Quantity: 2
Equipment Compliance: Yes
Surface Area Compliance: N/A

Total Findings: 2



Finding 1
The backboard graphics card is damaged - Replace

Finding 2
There is some minor damage to the surface - Monitor for any further deterioration and repair as required

4 - Very Low Risk

Item: Sign
Manufacturer: Hags
Surface Type: Bitmac
Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 1



Finding 1
This item is satisfactory - no work required -

6 - Low Risk

Item: Push Up Station
Manufacturer: Hags
Surface Type: Bitmac
Item Quantity: 1
Equipment Compliance: Yes
Surface Area Compliance: Yes

Total Findings: 1



Finding 1

This item is satisfactory - no work required -

6 - Low Risk

Item: Rower
Manufacturer: Hags
Surface Type: Bitmac
Item Quantity: 1
Equipment Compliance: Yes
Surface Area Compliance: Yes

Total Findings: 1



Finding 1

Bolt cap cover/s missing or damaged - Replace

6 - Low Risk

Item: Cycle
Manufacturer: Hags
Surface Type: Bitmac
Item Quantity: 1
Equipment Compliance: Yes
Surface Area Compliance: Yes

Total Findings: 1



Finding 1

This item is satisfactory - no work required -

8 - Low Risk

Item: Skier
Manufacturer: Hags
Surface Type: Bitmac
Item Quantity: 1
Equipment Compliance: Yes
Surface Area Compliance: Yes

Total Findings: 1



Finding 1

This item is satisfactory - no work required -

6 - Low Risk

Item:	Double Fitness Station
Manufacturer:	Hags
Surface Type:	Bitmac
Item Quantity:	1
Equipment Compliance:	Yes
Surface Area Compliance:	Yes
Total Findings:	1



Finding 1

This item is satisfactory - no work required -

8 - Low Risk

Item:	Health Walker
Manufacturer:	Hags
Surface Type:	Bitmac
Item Quantity:	1
Equipment Compliance:	Yes
Surface Area Compliance:	Yes
Total Findings:	1



Finding 1

This item is satisfactory - no work required -

6 - Low Risk

Item: Flat Bank
Manufacturer: Not Identified
Surface Type: Bitmac
Item Quantity: 1
Equipment Compliance: No
Surface Area Compliance: No

Total Findings: 2



Finding 1

The item has insufficient safety zone allowed as required by BS EN 14974; 6.4. This should equal at least 2.0 metres on this item - Monitor - No action given the risk assessment

Finding 2

The height of the barrier is less than 1200mm in contravention of BS EN 14974 - 6.2.6. This height must be achieved all around the platform and at a maximum distance of 300mm from the front of the platform. - Monitor - no reasonably practicable action given the risk assessment

8 - Low Risk

Item: Sign
Manufacturer: Not Identified
Surface Type: Grass
Item Quantity: 2
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 1



Finding 1

There are projecting bolt thread(s) present - Remove excess thread length and deburr or provide cap

8 - Low Risk

Item:	Grind Box
Manufacturer:	Not Identified
Surface Type:	Bitmac
Item Quantity:	1
Equipment Compliance:	Yes
Surface Area Compliance:	Yes
Total Findings:	1



Finding 1

This item is satisfactory - no work required -

8 - Low Risk

Item:	Fun Box
Manufacturer:	Not Identified
Surface Type:	Bitmac
Item Quantity:	1
Equipment Compliance:	No
Surface Area Compliance:	No
Total Findings:	2



Finding 1

The item has insufficient safety zone allowed as required by BS EN 14974; 6.4. This should equal at least 2.0 metres on this item - Monitor - No action given the risk assessment

Finding 2

There are differences in height exceeding 3mm on the rolling / riding surfaces in contravention of the requirements of BS EN 14974; - 6.2.4 - Take corrective action to ensure that the gaps between the joints do not exceed 3mm

8 - Low Risk

Item:	Grind Rail
Manufacturer:	Not Identified
Surface Type:	Bitmac
Item Quantity:	1
Equipment Compliance:	Yes
Surface Area Compliance:	Yes
Total Findings:	1



Finding 1

The item has been damaged - Monitor for any further deterioration and replace as required

8 - Low Risk

Item:	Quarter Pipe
Manufacturer:	Not Identified
Surface Type:	Bitmac
Item Quantity:	1
Equipment Compliance:	No
Surface Area Compliance:	Yes
Total Findings:	1



Finding 1

The height of the barrier is less than 1200mm in contravention of BS EN 14974 - 6.2.6. This height must be achieved all around the platform and at a maximum distance of 300mm from the front of the platform. - Monitor - no reasonably practicable action given the risk assessment

6 - Low Risk

Item:	Football Goal
Manufacturer:	Not Identified
Surface Type:	Grass
Item Quantity:	1
Equipment Compliance:	N/A
Surface Area Compliance:	N/A
Total Findings:	3



Finding 1

NB: We have undertaken a maintenance inspection only of the football goal(s); full load testing falls outside the scope of our inspection. - Implement load testing as required

Finding 2

The surface has eroded in some areas and may be slippery in wet conditions - Reinstate the surface

Finding 3

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding - Treat affected areas and repaint

Findings information

8 - Low Risk (Finding 1)

Item:	Ancillary Items - Site General	**Risk Level:**	L - Low Risk
Manufacturer:	Owner/Operator	**Surface:**	N/A





Finding: There is a potential conflict between the users of the basketball post and the users of the fitness equipment

Action: Monitor and take appropriate action if required

8 - Low Risk (Finding 1)

Item: Ancillary Items - Sign
Manufacturer: Not Identified
Risk Level: L - Low Risk
Surface: N/A





Finding: There are projecting bolt thread(s) present

Action: Remove excess thread length and deburr or provide cap

8 - Low Risk (Finding 1)

Item: Gates - Gate - Self Closing
Manufacturer: I.A.E. Fencing
Risk Level: L - Low Risk
Surface: Grass





Finding: There are trip hazards present

Action: Remove trip hazard

8 - Low Risk (Finding 2)

Item: Gates - Gate - Self Closing
Manufacturer: I.A.E. Fencing
Risk Level: L - Low Risk
Surface: Grass





Finding: The gate is closing too quickly (less than 4 seconds)

Action: Take corrective action to ensure that the gate closes in 4-8 seconds from 90 degrees

6 - Low Risk (Finding 1)

Item: Gates - Gate - Combination
Manufacturer: I.A.E. Fencing
Risk Level: L - Low Risk
Surface: Grass





Finding: There is no padlock on the maintenance gate

Action: Provide a padlock to secure the gate

6 - Low Risk (Finding 2)

Item: Gates - Gate - Combination
Manufacturer: I.A.E. Fencing
Risk Level: L - Low Risk
Surface: Grass





Finding: The gate has no drop bolt sleeves and/or drop bolts fitted

Action: Provide drop bolt sleeves and/or drop bolts

8 - Low Risk (Finding 1)

Item: Ancillary Items - Teenage Shelter
Manufacturer: Not Identified
Risk Level: L - Low Risk
Surface: Concrete





Finding: There are trip hazards at the edges of the surface

Action: Remove trip hazard

6 - Low Risk (Finding 2)

Item: Ancillary Items - Teenage Shelter
Manufacturer: Not Identified
Risk Level: L - Low Risk
Surface: Concrete





Finding: The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding

Action: Treat affected areas and repaint

6 - Low Risk (Finding 1)

Item: Swings - 1 Bay 2 Seat (Flat)
Manufacturer: Wicksteed Playgrounds
Risk Level: L - Low Risk
Surface: Grass Matrix Tiles





Finding: The seats are too close to each other as defined in BS EN 1176 Part 2; this is a low risk failure and no remedial action is required

Action: Monitor - No action given the risk assessment

8 - Low Risk (Finding 1)

Item: Rocking Equipment - See Saw
Manufacturer: Wicksteed Playgrounds
Risk Level: L - Low Risk
Surface: Grass Matrix Tiles





Finding: The torsion joint is very stiff and difficult to operate
Action: Repair or replace

8 - Low Risk (Finding 2)

Item: Rocking Equipment - See Saw
Manufacturer: Wicksteed Playgrounds
Risk Level: L - Low Risk
Surface: Grass Matrix Tiles





Finding: There are trip hazards present
Action: Remove trip hazard

6 - Low Risk (Finding 1)

Item: Activity Equipment - Activity Trail
Manufacturer: Wicksteed Playgrounds
Risk Level: L - Low Risk
Surface: Grass





Finding: The ropes/nets are worn/damaged in places

Action: Monitor for any further deterioration and repair or replace as required

5 - Very Low Risk (Finding 2)

Item: Activity Equipment - Activity Trail
Manufacturer: Wicksteed Playgrounds
Risk Level: V - Very Low Risk
Surface: Grass





Finding: The connecting links are in excess of 8.6mm and less than 12mm and fail the requirements of BS EN 1176 Part 1; clause 4.2.13, Chains

Action: Monitor - No action given the risk assessment

6 - Low Risk (Finding 3)

Item:	Activity Equipment - Activity Trail	**Risk Level:**	L - Low Risk
Manufacturer:	Wicksteed Playgrounds	**Surface:**	Grass







Finding: The surface has subsided in some areas

Action: Monitor for any further deterioration and repair as required

6 - Low Risk (Finding 1)

Item:	Activity Equipment - Multi Play (Junior)	**Risk Level:**	L - Low Risk
Manufacturer:	Wicksteed Playgrounds	**Surface:**	Grass Matrix Tiles





Finding: The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding

Action: Treat affected areas and repaint

5 - Very Low Risk (Finding 2)

Item:	Activity Equipment - Multi Play (Junior)	**Risk Level:**	V - Very Low Risk
Manufacturer:	Wicksteed Playgrounds	**Surface:**	Grass Matrix Tiles







Finding: The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 for head and neck entrapment in the netting due to a loose rope connector

Action: Adjust and secure the rope connector to remove the entrapments

6 - Low Risk (Finding 3)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Wicksteed Playgrounds
Risk Level: L - Low Risk
Surface: Grass Matrix Tiles





Finding: The ropes/nets are worn/damaged in places

Action: Monitor for any further deterioration and repair or replace as required

8 - Low Risk (Finding 4)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Wicksteed Playgrounds
Risk Level: L - Low Risk
Surface: Grass Matrix Tiles





Finding: The adjacent foliage is overhanging the falling space

Action: Cut back and maintain a clear falling space

10 - Low Risk (Finding 1)

Item:	Multi Use Games Area - Basketball Post	**Risk Level:**	L - Low Risk
Manufacturer:	Adidas	**Surface:**	Bitmac





Finding: The backboard graphics card is damaged

Action: Replace

4 - Very Low Risk (Finding 2)

Item:	Multi Use Games Area - Basketball Post	**Risk Level:**	V - Very Low Risk
Manufacturer:	Adidas	**Surface:**	Bitmac





Finding: There is some minor damage to the surface

Action: Monitor for any further deterioration and repair as required

6 - Low Risk (Finding 1)

Item: Outdoor Fitness Equipment - Rower
Manufacturer: Hags
Risk Level: L - Low Risk
Surface: Bitmac





Finding: Bolt cap cover/s missing or damaged

Action: Replace

6 - Low Risk (Finding 1)

Item: Wheeled Sports - Flat Bank
Manufacturer: Not Identified
Risk Level: L - Low Risk
Surface: Bitmac





Finding: The item has insufficient safety zone allowed as required by BS EN 14974; 6.4. This should equal at least 2.0 metres on this item

Action: Monitor - No action given the risk assessment

6 - Low Risk (Finding 2)

Item: Wheeled Sports - Flat Bank
Manufacturer: Not Identified
Risk Level: L - Low Risk
Surface: Bitmac





Finding: The height of the barrier is less than 1200mm in contravention of BS EN 14974 - 6.2.6. This height must be achieved all around the platform and at a maximum distance of 300mm from the front of the platform.

Action: Monitor - no reasonably practicable action given the risk assessment

8 - Low Risk (Finding 1)

Item: Ancillary Items - Sign
Manufacturer: Not Identified
Risk Level: L - Low Risk
Surface: Grass





Finding: There are projecting bolt thread(s) present

Action: Remove excess thread length and deburr or provide cap

6 - Low Risk (Finding 1)

Item:	Wheeled Sports - Fun Box	**Risk Level:**	L - Low Risk
Manufacturer:	Not Identified	**Surface:**	Bitmac





Finding: The item has insufficient safety zone allowed as required by BS EN 14974; 6.4. This should equal at least 2.0 metres on this item

Action: Monitor - No action given the risk assessment

8 - Low Risk (Finding 2)

Item:	Wheeled Sports - Fun Box	**Risk Level:**	L - Low Risk
Manufacturer:	Not Identified	**Surface:**	Bitmac







Finding: There are differences in height exceeding 3mm on the rolling / riding surfaces in contravention of the requirements of BS EN 14974; - 6.2.4

Action: Take corrective action to ensure that the gaps between the joints do not exceed 3mm

8 - Low Risk (Finding 1)

Item: Wheeled Sports - Grind Rail
Manufacturer: Not Identified
Risk Level: L - Low Risk
Surface: Bitmac





Finding: The item has been damaged

Action: Monitor for any further deterioration and replace as required

8 - Low Risk (Finding 1)

Item: Wheeled Sports - Quarter Pipe
Manufacturer: Not Identified
Risk Level: L - Low Risk
Surface: Bitmac





Finding: The height of the barrier is less than 1200mm in contravention of BS EN 14974 - 6.2.6. This height must be achieved all around the platform and at a maximum distance of 300mm from the front of the platform.

Action: Monitor - no reasonably practicable action given the risk assessment

0 - Risk Assessment not Undertaken (Finding 1)

Item: Multi Use Games Area - Football Goal
Manufacturer: Not Identified
Risk Level: N - Risk Assessment not Undertaken
Surface: Grass





Finding: NB: We have undertaken a maintenance inspection only of the football goal(s); full load testing falls outside the scope of our inspection.

Action: Implement load testing as required

6 - Low Risk (Finding 2)

Item: Multi Use Games Area - Football Goal
Manufacturer: Not Identified
Risk Level: L - Low Risk
Surface: Grass





Finding: The surface has eroded in some areas and may be slippery in wet conditions

Action: Reinstate the surface

6 - Low Risk (Finding 3)

Item:	Multi Use Games Area - Football Goal	**Risk Level:**	L - Low Risk
Manufacturer:	Not Identified	**Surface:**	Grass





Finding: The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding

Action: Treat affected areas and repaint